

# RPM Indicator



IM 1900 Series RPM indicators are useful for indicating wide range of rotating machine speeds. These are non contact type Digital tachometers which work with external proximity or optical sensor to measure the revolution speed either in terms of RPM (revolutions per minute) or RPS (revolutions per second) or in desired units like metres per minute etc.

These instruments are also known as Speed Indicators / Frequency Indicators / Digital Tachometers.

## SPECIFICATIONS

- 4 / 6 digit LED display
- RPM Range 0.1 to 9999 / 999999 RPM. Very low RPM Indication right upto 0.01 RPM etc is possible
- Floating decimal point
- Input from proximity sensor / optical encoder / limit switch / tachometer
- RS232 / RS485 Modbus Interface
- Supply 230 V / 12 V DC / 24 V DC / 48 V DC / 110 V etc
- Panel mount type indicator in 96x96 mm size

## VARIOUS OPTIONS

Indicators are available with various options like :

- ! Direct display in various units like metres / min, litres / hr etc
- ! High / Low alarms
- ! PC connectivity / Modbus Interface
- ! Display sizes from 0.5 to 5 inches
- ! Master Slave display units



## KVAR Technologies Pvt. Ltd.

68, Kakad Ind. Estate, Off L.J.Road, Mahim, Mumbai 400 016, India  
Ph: +91 22 2431 2031 Fax: 2432 2320 Email : sales@kvartech.com

[www.kvartech.com](http://www.kvartech.com)

[www.dataloggersindia.com](http://www.dataloggersindia.com)

[www.ajinkya.in](http://www.ajinkya.in)

[www.amperehourmeter.com](http://www.amperehourmeter.com)  
[www.displaysystemsindia.com](http://www.displaysystemsindia.com)